



Name : .....  
Roll No. : .....  
Invigilator's Signature : .....

**CS/B.TECH(EE/EEE/ICE/PWE)(NEW)/SEM-4/EE-402/2012**

**2012**

**ELECTRICAL AND ELECTRONIC MEASUREMENT**

Time Allotted : 3 Hours

Full Marks : 70

*The figures in the margin indicate full marks.*

*Candidates are required to give their answers in their own words  
as far as practicable.*

**GROUP – A**

**( Multiple Choice Type Questions )**

1. Choose the correct alternatives for any *ten* of the following :

$$10 \times 1 = 10$$

- i) In measurement systems, which of the following static characteristic(s) is/are desirable ?
  - a) Accuracy
  - b) Sensitivity
  - c) Reproducibility
  - d) All of these.
- ii) Frequency can be measured by using
  - a) Maxwell bridge
  - b) Schering bridge
  - c) Heaviside-Campbell bridge
  - d) Wien's bridge.



- iii) In a CRT the focusing anode is located
- a) between pre-accelerating and accelerating anodes
  - b) after accelerating anode
  - c) before pre-accelerating anode
  - d) none of these.
- iv) LVDT is a
- a) capacitive transducer
  - b) resistive transducer
  - c) inductive transducer
  - d) none of these.
- v) The potentiometer is basically an instrument of
- a) digital type
  - b) deflection type
  - c) null type
  - d) recording type.



- vi) A megger is used for measurement of
- a) low valued resistance
  - b) medium valued resistances
  - c) high valued resistances
  - d) all of these.
- vii) Murray loop test is used for location of
- a) short circuit fault on a cable
  - b) ground fault on a cable
  - c) both (a) and (b)
  - d) open circuit fault.
- viii) Calibration of DC potentiometer is done with the help of standard cell of voltage
- a) 1.5 V
  - b) 1.01864 V
  - c) 1.001864 V
  - d) 1.0864 V.



- ix) Creeping is observed in
- a) watt-hour meter
  - b) wattmeter
  - c) ammeter
  - d) power factor meter.
- x) The secondary of a CT is
- a) never left open circuited
  - b) never left short circuited
  - c) always kept open circuited
  - d) none of these.
- xi) The high torque to weight ratio in an analog instrument indicates
- a) high friction loss
  - b) low friction loss
  - c) nothing as regards friction loss
  - d) none of these.



**GROUP – B**

**( Short Answer Type Questions )**

Answer any *three* of the following.  $3 \times 5 = 15$

2. Define the terms Accuracy, Precision, Resolution, Drift and Relative limiting error.
3. Explain the difference between Dynamometer type wattmeter and induction type wattmeter.
4. What is phantom loading ? Explain with an example how it is more advantageous than testing with direct loading.
5. Show that driving torque in a moving iron instrument is given by  $T_D = 0.5[I^2 dL/d\theta]$ . Where the symbols have their usual meaning.
6. Draw and explain how low resistance is measured using Kelvin's Double bridge.

**GROUP – C**

**( Long Answer Type Questions )**

Answer any *three* of the following.  $3 \times 15 = 45$

7. a) Describe in brief the construction and working principle of a single phase induction type energy meter.  
b) What is Blondel's theorem ?




- c) A single phase kWhr meter makes 500 revolutions per kWhr. It is found on testing that it is making 40 revolutions in 58.1 seconds at 5 kW load. Find out the percentage of error. 8 + 3 + 4

8. a) Explain the functional block diagram of CRO with neat diagram.
- b) What is Lissagous figure ? Explain how phase & frequency can be measured using this figures.
- c) What are the differences between dual beam CRO & dual trace CRO ? What is the function of delay line ?

$$6 + ( 2 + 3 ) + ( 3 + 1 )$$

9. a) Draw the circuit diagram of DC potentiometer & explain how it works.
- b) How can potentiometer be used for
- i) calibration of voltmeter
  - ii) calibration of wattmeter.
- c) What are the adjustment of induction type AC energy meter ? 5 + 5 + 5



10. Deduce the expression of torque of electrodynamicometer type instrument. Why multiplier is used with PMMC instrument ? What do you mean by sensitivity of PMMC instrument ? Why sensitivity of electrodynamicometer type instrument is low ? Why the scale of moving iron instrument is cramped at lower end ? 6 + 2 + 2 + 2 + 3

11. Write short notes on any *three* of the following : 3 × 5

- a) Digital Multimeter
- b) Rectifier type instrument
- c) Q-meter
- d) Megger
- e) Piezoelectric transducer
- f) LVDT.

=====